

Aanderaa Data Instruments AS

Sanddalsringen 5b, Postboks 103 Midtun, 5843 Bergen, Norway
Tel +47 55 60 48 00 aanderaa.info@xylem.com

Seaguard II Image - v 3.0.228 - 12.10.2023

Summary: Delete data folder bugfix

Bug Fix

- Delete directory failed when containing sub-directories

Seaguard II Image - v 3.0.227 - 28.04.2023

Summary: Support for both virtual comport and activesync

New Functionality

- Added support for switching between USB function as virtual comport and ActiveSync

Seaguard II Image - v 3.0.224 - 03.01.2023 (Release)

Summary: USB virtual serial port replacement for ActiveSync

New Functionality

- USB will now be used as virtual serial port instead of ActiveSync

Bug Fix

- ModemManager: Iridium m_IR rebootWaitTime was not read from the configuration



Seaguard II Image - v 3.0.206 - 28.04.2021 (Release)

Summary: Smartguard (Image 2.1.173) and Seaguard II Sync

New Functionality

- Smartguard (Image 2.1.173) and Seaguard II Sync

Seaguard II Image - v 3.0.205 - 22.01.2020 (Release)

Summary: Added Input Channel with Filter option to custom data format for serial sensor.

Improvement

- Added Input Channel with Filter option to custom data format for serial sensor.

Seaguard II Image - v 3.0.204 - 17.10.2019

Summary: Fix bug in ReSync of SD Card having different hidden sector offset.

Bug Fix

- Fix bug in ReSync of SD Card having different hidden sector offset.

Seaguard II Image - v 3.0.203 - 08.04.2019 (Release)

Summary: Fix the modemManager so it support profile in customformat. It use the vector as id, when it generate a connection object for real-time collector

Also fix in iridium so it l postbone the transfer of data after modem powerup.

It use the Warm up Time to add delay from power up to the data is sendt to the modem.



Improvement

- Add Power setting Warmup time to Iridium data deliver schedule, so that the modem can receive the characters.

Bug Fix

- Fix the Modem manager so it support profile in customformat.